

# Failure analysis of broken turbo wheel flange

J. Bendayan

Dayanson Shaked Ltd, Caesarea, Israel  
E-mail: shaked00@013net.net

## Keywords

Failure analysis, welding, fatigue, wheel flange

## 1. Introduction

In our days failure analysis is a must for every product or process. Each of them has different modes of failure.

An analysis of potential failures helps the designers to focus on and understand the impact of potential process or product risks and failures [1]. In some cases this has to be performed after the product is in service in order to correct production errors [2]. The case presented in this paper refers to such an example. A turbo wheel with a broken flange was delivered for analysis by a customer. According to the customer the wheel was used in 3-axle trailer. The failure was reported in the company Service Report and leaded to production stop. The request was to perform failure analysis of the turbo wheel flange.

## 2. Inspection phases performed

### 2.1. Visual inspection

The wheel with the broken off crown of the flange is shown in Fig. 1. The central part of the flange is shown in Fig. 2. The flange crown consists of 10 lugs with the holes for fastening the flange to the wheel. All lugs broke off at their base.



Figure 1. View of the wheel with broken off flange crown.

The typical fracture surface of the lug is shown in Fig. 3. It is characteristic of fatigue fracture initiated at one of the sides and propagated till about a half of the lug thickness up to the final fracture.

### 2.2. Chemical analysis

The chemical composition of the broken part was investigated using a Spectro Lab S type spectroscope. Special specimen for the analysis was prepared by melting. The analysis results are presented in Table 1.



Figure 2. View of the failed flange – the crown is broken off.



Figure 3. Close-up of the fracture surface of the flange.

The analysis results indicate that the chemical composition of the flange corresponds to ductile (nodular) cast iron SAE J434.

### 2.3. Metallographic analysis

The microstructure of the flange material was investigated in a metallographic section prepared close to the fracture surface. After grinding and polishing the section was investigated using an

Table 1. Chemical analysis results.

Elements, [%]	Analysis	SAE J434 Grade D5506
C	3.18	3.20± 4.10
Si	2.59	1.80± 3.00
Mn	0.33	0.10± 1.00
P	0.019	–
S	0.014	0.005± 0.033
Fe	balance	balance

optical microscope. The spheroidal graphite of type I according to SAE J434 was found (Fig. 4). After etching in Nital 2% the microstructure metallic matrix consisting of ferrite and pearlite




Figure 4. Nodular graphite form of the flange material.

was revealed (Fig. 5a, 5b). As can be seen from these photographs the pearlite content varies from about 10 to 40%. The graphite form and the microstructure of the metallic matrix correspond to the ductile cast iron SAE J434 Grade 4512 to Grade 5506.

### 2.4. Brinell hardness test

The hardness of the flange material was measured with the 3000 kg test load and the indenter of 10 mm diameter.


The measured hardness was in the range: 177±179 HB. This hardness corresponds to the hardness of the ductile cast iron SAE J434 Grade 4512 (156±217 HB). It does not correspond to the Grade 5506 (187±255 HB).

Table 2. Tensile test results.


	Specimen's diameter [mm]	Yield stress [MPa]	Ultimate stress [MPa]	Elongation, L = 25 mm [%]
Test ASTM E8 / E8M - 13a	6.02	346	531	8.3
SAE J434 Grade D5506	6.02	379	552	6.0
SAE J434 Grade D4512	6.02	310	448	12.0

### 2.5. Tensile test

Tensile test was performed on a specimen made from the flange material. The test was performed using an Instron 4400R testing machine. The test results are presented in Table 2.



a)



b)

Figure 5. Ferritic-pearlitic microstructure of the metallic matrix:  
a – 10% pearlite content, b – 40% pearlite content.

The test results indicate that the mechanical properties of the flange material are between the typical values of the ductile cast iron of the Grades D5506 and Grade 4512.

### 2.6. Fractographic analysis of the fracture surface by SEM

The morphology of the fracture surface was examined using a Philips XL30 scanning electron microscope (SEM). The fatigue striations found in the fatigue zone of the fracture surface are shown in Fig. 6. The morphology of the fracture surface in the final fracture zone consists of large shallow

dimples formed from graphite spheroids (Fig. 7). At higher magnification small dimples were also found (Fig. 8). This morphology is characteristic of final fracture of the ductile material [3].




Figure 6. Fatigue striations found in the fatigue zone of the flange fracture surface.




Figure 7. Final fracture zone at low magnification.




Figure 8. Final fracture zone at high magnification.

### 3. Conclusion

- The failed turbo wheel flange was manufactured of ductile cast iron corresponding to SAE J434.
- According to microstructure and hardness the material corresponds to Grade 4512, but has a decreased elongation.

According to tensile mechanical properties the material can be qualified as Grade 5506.

- The microstructure of the metallic matrix is not uniform: the pearlite content varies from 10% to 40%. The areas with decreased pearlite content have decreased local strength, which manifest itself in decreased fatigue strength.
- The failure of turbo wheel flange is a result of fatigue crack initiation and propagation. The lifetime of the product was reached.

### References

- [1]. \*\*\*, ASM Metals\_Handbook Volume 11: Failure Analisys and Prevention, ASM International 2002
- [2]. Jones, D.R.H., Failure Analysis Case Studies, II, Pergamon Elsevier Science, 2001, ISBN 0-08 -043959-4
- [3]. \*\*\*, ASM Metals Handbook, vol. 11, Failure Analysis and Prevention, ASM International, 2002, ISBN: 0-87170-704-7



**Welding & Material Testing**

Sudarea și încercarea Materialelor

about editorial committee reviewers authors archive contact media

**Archive 2013**

**1-2013**

Superposition of effects for the mechanical structures fatigue calculation  
(V. Jneacu, N. Teodorescu)

Application of Risk Based Inspection to heat exchangers of a chemical plant for heavy water production  
(A.C. Murariu, N. Peagă)

Concerns on the development of the amorphous alloys in bulk and ribbon form  
(V.-A. Ţerban, C. Cootean)

Design elements used in the construction of a wheeled mini-robot destined for special applications  
(S.M. Petrișor, G. Bărsan, A.I. Husto)

New variants of the overlaying processes  
(V. Verbäch)

**2-2013**

Plasma welding – State of the Art  
(D. Bohrme, H. Cramer)

Optimization of welding of wire crossings using energetic method  
(E. Forgaica, G. Moț, J. Gyeviki, I. Biró)

Testing the wear on the hardened surface layers  
(C. Sălăeanu, M. Demian, G. Demian)

Comparative study regarding the generation of circular profiles through cutting  
(O. Bologa, G. Racz, R. Breaz, M. Crengăniș)

Application possibilities of the friction stir welding process to dissimilar aluminum alloys  
(R. Cojocan, L. Botăș, C. Cluciă)

**3-2013**

Optimization of the electrode processing methodology for spot welding of aluminium  
(M. Mueller, H. Cramer, T. Bischoff)

Analysis of the influence of tensile loading rate and artificial aging on the mechanical properties of Vinnol-based polymeric membranes

Copyright © 2013 ISIM Timisoara. All rights reserved.

**www.bid-isim.ro**

**TRANSAGRO**

Exploratory research on the opportunities to increase the life time and efficient recycling of the active components of agricultural equipment

Home | Objectives | Activities & Results | Events | Contact

**About**

Title of the project: Exploratory research on the opportunities to increase the life time and efficient recycling of the active components of agricultural equipments

Project Acronym: TRANSAGRO

Priority axis: Strengthen social and economic cohesion of the border area

Key area of intervention: 2.2: Promotion of co-operation in the field of R&D and innovation

Action: 2.2.2: Realization of joint research projects

Planned project starting and ending date: 01/10/2012 - 30/09/2013

Sources of funding: Requested grant: 360.726 € (96.5%); Own contribution: 13.074 € (3.5%)

**Lead Partner**

**ISIM**  
National Research and Development Institute for Welding and Materials Testing – ISIM Timisoara, Romania

**Partner**

MÉRNÖKI KARI TUDOMÁNYEGYETEM Szegedi Tudományegyetem, Hungary

**Problems and challenges**

Regarding soil cultivation, there is a constant problem of wear. The wear of agricultural equipment (e.g. edge tools, plough-share), their change and repair cause severe challenges. The primary cause of wear on the agricultural equipments is the soil. Soil regional variations cause different wear rates. Given the similar characteristics of soil of the Southern Great Plain from Hungary and Banat,

**www.transagro-huro.ro**